

D-72336 Balingen E-Mail: info@kern-sohn.com Tel.: +49-[0]7433- 9933-0 Fax: +49-[0]7433-9933-149 Internet: www.kern-sohn.com

Operating manual Precision balance

KERN EHA

Version 1.1 2020-06 GB





EHA-BA-e-2011



KERN EHA

Version 1.1 2020-06
Operating manual
Precision balance

1. Technical data

| KERN | EHA 500-2 | EHA 500-1 | EHA 1000-1 | |
|--------------------------------------|---------------------------------------|------------------------|-----------------------|--|
| Item no./ Type | TEHA 500-2-A | TEHA 500-1-A | TEHA 1000-1-A | |
| Readability (d) | 0.01 g | 0.1 g | 0.1 g | |
| Weighing range (max) | 500 g | 500 g | 1000 g | |
| Adjustment weight, not added (class) | 200 g (F2); 500 g (F2) | 200 g (M1); 500 g (M1) | 500 g (M1); 1 kg (M1) | |
| Weighing surface (mm) | Ø 105 | | | |
| Operating temperature | + 5° C + 40° C | | | |
| Humidity of air | max 80% air humidity (non-condensing) | | | |
| Batteries | 2 x 1.5 V AA (Runtime rating 400 hrs) | | | |


| KERN | EHA 3000-1 | EHA 3000-0 | |
|--------------------------------------|---------------------------------------|----------------------|--|
| Item no./ Type | TEHA 3000-1-A | TEHA 3000-0-A | |
| Readability (d) | 0.1 g | 1 g | |
| Weighing range (max) | 3000 g | 3000 g | |
| Adjustment weight, not added (class) | 1 kg (F2); 3 kg (F2) | 1 kg (M1); 3 kg (M1) | |
| Weighing surface (mm) | 120 x 120 (square) | | |
| Operating temperature | + 5° C + 40° C | | |
| Humidity of air | max 80% air humidity (non-condensing) | | |
| Batteries | 2 x 1.5 V AA (Runtime rating 400 hrs) | | |

2. Scope of delivery

- Pocket scale
- 4 Adjustment feet
- Mains adapter
- Operating manual

2 EHA-BA-e-2011

3. Keyboard overview



| ON OFF | Switch on/off |
|--------|---------------------------|
| MODE | Switch-over weighing unit |
| TARE | Taring / Setting to zero |
| PCS | Parts counting |
| CAL | Adjustment |

4. Adjustment

- Arrange adjustment weight (see chap. 1).

 Info about adjustment weights can be found on the Internet at: http://www.kern-sohn.com
- ⇒ Ensure that there are no objects on the weighing pan.
- ⇒ In weighing mode keep **CAL** button pressed, the maximum weight of the balance is displayed.
- ⇒ Press **CAL** button again, CAL will be shortly displayed, after that a weight value will appear flashing. Place a weight of this size. The weight value of the adjustment weight appears flashing. Remove weight.
- ⇒ Place adjustment weight. Wait until **PASS**, followed by the weight value of the placed adjustment weight will be displayed. After that the adjustment will be finished successfully. The balance is now in weighing mode.
- □ In case of a diverging display the adjustment has failed. Repeat adjustment process.

EHA-BA-e-2011 3

5. Operation

Weighing:

⇒ Place the balance on a firm, level surface. Level balance with foot screws until the air bubble of the water balance is in the prescribed circle. Check levelling regularly





- To switch-on, press the **ON/OFF** button, the maximum weight of the balance will be displayed for a short time. After that the weight display appears, the balance is now ready for weighing. If required, set to zero by using **TARE** button.
- ⇒ Place load on pan and read the weighing result.
- ⇒ Use the **MODE** button to switch over into the available weighing settings.



Taring:

- ⇒ Place the empty weighing container.
- ⇒ Press the TARE button, the zero display disappears.
- Weigh the material, the net weight will be indicated.
- ⇒ When the balance is unloaded the saved taring value is displayed with negative sign.
- ⇒ To delete the stored tare value, remove load from weighing pan and press the **TARE** button.

Parts counting:

- In weighing mode press the **PCS** button for 2 seconds, the balance changes into counting mode, 25 PCS will be displayed.
- ⇒ Press the MODE button to select the desired reference number of pieces (selectable options include 25, 50, 75, 100)
- ⇒ While PCS is flashing, place a reference which corresponds to the selected number of pieces
- ⇒ Remove reference.
- If necessary, tare the empty balance container.
- ⇒ Place counted pieces on pan and read the quantity of pieces.
- ⇒ Use **MODE** button to return to the weighing mode.

6. Important Notes

- Do not overload balance.
- The occurrence of electromagnetic fields may result in major display deviations. Then change location.
- Avoid high air humidity, vapours and dust.
- Do not bring the balance directly in contact with liquids.
- Do not leave permanent load on the weighing pan.
- Never operate balance in explosive environment. The serial version is not explosion protected.
- Check the balance regularly with external test weights.
- Warranty claims will be voided when the housing is opened.

4 EHA-BA-e-2011

7. Error reports

| Error message | Description | Corrective measures |
|---------------|--|--|
| Frr | Load cell defective | Replace load cell |
| | Operating error | Replace battery and readjust the balance |
| | | |
| 0-Ld | Load cell defective | Replace load cell |
| | Overload | Weighing only within the maximum load |
| | Adjustment with wrong adjustment weight | Adjustment with correct adjustment weight |
| | | |
| UNSŁ | Load cell defective | Replace load cell |
| | Balance not correctly levelled | Place the balance on a level, even surface and level it using the four adjustment feet in a way that the air bubble of the spirit level is inside the circle |
| | The balance is in an environment with strong air draught or electromagnetic fields | Improve the environmental conditions |
| | | |
| Lo | Capacity of battery exhausted | Insert new battery |

8. Declaration of conformity

The current EC/EU Conformity declaration can be found online in:

www.kern-sohn.com/ce

EHA-BA-e-2011 5