Tips for an Accurate Measurement

- It is important that the sample does not contain any debris.
- Whenever the cuvette is placed into the measurement cell, it must be dry outside, and completely free of fingerprints, oil and dirt. Wipe it thoroughly with H1731318 or a lint-free cloth prior to insertion
- Shaking the cuvette can generate bubbles, causing higher readinas. To obtain accurate measurements, remove such bubbles by swirling or by gently tapping the cuvette.
- Do not let the reacted sample stand for too long after reagent is added, as accuracy will be affected.
- · After the reading it is important to immediately discard the





Battery Management

To save the battery, the instrument shuts down after 10 minutes of non-use and 2 minutes after reading

One fresh battery lasts for a minimum of 5000 measurements. When the battery is dead the instrument will display "bAd" then "bAt" for 1 second and then turns off.

To restart the instrument, the battery must be replaced with a new one.

To replace the instrument's battery:

- Turn the instrument off by holding the button until the meter shuts off.
- Turn the instrument upside down and remove the battery cover with a screwdriver.



- Remove the battery from its location and replace it with a new one, inserting the negative end first
- Insert the battery cover and replace the screw with a screwdriver.

Recommendations for Users

Before using Hanna Instruments products, make sure that they are entirely suitable for your specific application and for the environment in which they are used. Any variation introduced by the user to the supplied equipment may degrade the instrument's performance. For yours and the instrument safety do not use or store the instrument in hazardous environments.

Accessories

Reagent Sets

| HI775-26 | Reagents for 25 Alkalinity tests, 1 syringe and 1 tip |
|-------------------|---|
| Other Accessories | |
| HI775-11 | Alkalinity Certified Standard Kit |
| HI731318 | Cloth for wiping cuvettes (4 pcs.) |
| HI731321 | Glass cuvettes and Seal Cap for Checker® HC Colorimeters (4 pcs.) |
| HI731225 | Cuvette Black Cap for Checker® HC Colorimeters (4 pcs.) |
| HI731353 | Cuvette seal cap for Checker® HC Colorimeters (4 pcs.) |
| H1740028P | 1.5V AAA batteries (12 pcs.) |
| H1740142P | 1 mL graduated syringe with tip (10 pcs.) |
| HI93703-50 | Cuvette cleaning solution (230 mL) |
| HI93755-53 | Chlorine Remover |
| | |

Warranty

H1775 is warranted for a period of one year after date of purchase against defects in workmanship and materials when used for their intended purpose and maintained according to instructions. This warranty is limited to repair or replacement free of charge. Damage due to accidents, misuse, tampering or lack of prescribed maintenance is not covered. If service is required, contact your local Hanna Instruments Office. If under warranty, report the model number, date of purchase, serial number and the nature of the problem. If the repair is not covered by the warranty, you will be notified of the charges incurred. If the instrument is to be returned to Hanna Instruments, first obtain a Return Goods Authorization number from the Technical Service department and then send it with shipping costs prepaid. When shipping any instrument, make sure it is properly packed for complete protection.

INSTRUCTION MANUAL

HI775 Alkalinity





Thank You

Thank you for choosing a Hanna Instruments product. Please read this instruction manual carefully before using the instrument.

For more information about Hanna Instruments and our products, visit www hannainst com

For technical support, contact your local Hanna Instruments Office or e-mail us at tech@hannainst.com.

Find your local Hanna Instruments Office on www.hannainst.com.

Preliminary Examination

Please examine this product carefully. Make sure that the instrument is not damaged. If any damage occurred during shipment, please contact your local Hanna Instruments Office. Each H1775 meter is supplied complete with:

- Sample Cuvettes and Caps (2 pcs.)
- · Reagents for 25 tests
- 1 mL syringe with tip
- 1.5V AAA Battery (1 pc.)
- Instruction Manual and Quick Reference Guide

Specifications

| Range | 0 to 500 ppm |
|----------------|--|
| Resolution | 1 ppm |
| Accuracy | \pm 5 ppm \pm 5% of reading @25 °C/77 °F |
| Light Source | Light Emitting Diode @610 nm |
| Light Detector | Silicon Photocell |
| Method | Colorimetric method. The reaction causes a distinctive range of colors from yellow to blue to develop. This meter has been developed to work with fresh water samples. |
| Environment | 0 to 50 °C (32 to 122 °F); max 95% RH non-condesing |
| Battery Type | 1.5V AAA (1 pc.) |
| Auto-Shut off | After 10 minutes of non-use and 2 minutes after reading |
| Dimensions | 86.0 x 61.0 x 37.5 mm (3.4 x 2.4 x 1.5") |
| Weight | 52 g (1.84 oz.) |

Functional Description



Errors and Warnings



Light High: There is too much light to perform a measurement. Please check the preparation of the zero cuvette.



Light Low: There is not enough light to perform a measurement. Please check the preparation of the zero cuvette.



Inverted Cuvettes: The sample and the zero cuvette are inverted.



Under Range: A blinking "O" indicates that the sample absorbs less light than the zero reference. Check the procedure and make sure you use the same cuvette for reference (zero) and measurement.



Over Range: A flashing value of the maximum concentration indicates the reading is over range. Dilute the sample and re-run the test.




Battery Low: The battery must be replaced soon.



Dead Battery: This indicates that the battery is dead and must be replaced. Once this indication is displayed, normal operation of the instrument will be interrupted. Change the battery and restart the meter.

Measurement Procedure

- . Turn the meter on by pressing the button. All seaments will be displayed. When the display shows "Add". "C.1" with "Press" blinking, the meter is readv.
- Fill the cuvette with 10 mL of unreacted sample and replace the cap. Place the cuvette into the meter and close the meter's cap.
- Press the button. When the display shows "Add", "C.2" with "Press" blinking, the meter is zeroed.





Note: Pay attention not to spill reagent otherwise full color development may be inhihited

Press the button. The instrument directly displays the concentration of alkalinity in ppm of CaCO_a. Alkalinity conversion:



The meter automatically turns off after 2 minutes



























Hanna Instruments reserves the right to modify the design, construction or appearance of its products without advance notice.